

MACOM
Partners from RF to Light

Aeroflex (MACOM Technology Solutions)

MACP-011036

부품 번호:	MACP-011036
제조업체 / 브랜드:	Aeroflex (MACOM Technology Solutions)
제품 설명	RF DIR COUPLER 5MHZ-1.2GHZ 6SMD
데이터 시트:	MACP-011036.pdf
RoHS 상태	무연 / RoHS 준수
재고 상태	4034 pcs stock
에서 운송된다	홍콩
선적 방법	DHL/Fedex/TNT/UPS/EMS



[견적 요청](#)

이미지는 표현 일 수 있습니다. 제품 세부 사항은 사양을 참조하십시오.

MACP-011036의 명세

부품 번호	MACP-011036
제조사	Aeroflex (MACOM Technology Solutions)
기술	RF DIR COUPLER 5MHZ-1.2GHZ 6SMD
무연 여부 / ROHS 준수 여부	무연 / RoHS 준수
사용 가능한 양	4034 pcs
데이터 시트	MACP-011036.pdf
제조업체 장치 패키지	6-SMD
연속	-
반사 손실	-22dB
전력 - 최대	0.5W
포장	Original-Reel®
패키지 / 케이스	6-SMD
다른 이름들	1465-1809-6
수분 민감도 (MSL)	1 (Unlimited)
무연 여부 / ROHS 준수 여부	Lead free / RoHS Compliant
격리	34dB
삽입 손실	-
회수	5MHz ~ 1.2GHz
상세 설명	RF Directional Coupler General Purpose 5MHz ~ 1.2GHz 16dB 0.5W 6-SMD
커플 링 팩터	16dB
커플러 유형	Standard
응용 프로그램	General Purpose

관련 태그

Aeroflex (MACOM Technology Solutions) MACP-011036	MACP-011036 대리점	MACP-011036 공급 업체
MACP-011036 가격	MACP-011036 사진	MACP-011036 이미지
MACP-011036 PDF 데이터 시트	MACP-011036 데이터 시트 다운로드	MACP-011036 데이터 시트
MACP-011036 주식	MACP-011036 구입	Aeroflex (MACOM Technology Solutions) MACP-011036 구입
Aeroflex (MACOM Technology Solutions) MACP-011036	Aeroflex (MACOM Technology Solutions) 공급 업체	Aeroflex (MACOM Technology Solutions) 대리점
Aeroflex (MACOM Technology Solutions) MACP-011036	Aeroflex Circuit Technology MACP-011036	Aeroflex MACP-011036
Aeroflex (MACOM Technology Solutions) MACP-011036	Aeroflex Metelics, Division of MACOM MACP-011036	M/A-Com Technology Solutions MACP-011036
Metelics (MACOM Technology Solutions) MACP-011036	MACOM Technology Solutions MACP-011036	

관련 상품

<p>MACP-011015 제조사: Aeroflex (MACOM Technology Solutions) 기술: RF DIR COUPLER 40MHZ-1.25GHZ 5SMD 재고: 24969 pcs</p> <p>RFQ</p>	<p>MACP-011034 제조사: Aeroflex (MACOM Technology Solutions) 기술: RF DIR COUPLER 5MHZ-1.2GHZ 6SMD 재고: 34659 pcs</p> <p>RFQ</p>
<p>MACP-011035 제조사: Aeroflex (MACOM Technology Solutions) 기술: RF DIR COUPLER 5MHZ-1.2GHZ 6SMD 재고: 31816 pcs</p> <p>RFQ</p>	<p>MACP-010563-001SMB 제조사: Aeroflex (MACOM Technology Solutions) 기술: EVAL BOARD FOR MACP-010563-TR100 재고: 4608 pcs</p> <p>RFQ</p>
<p>MACP-011014 제조사: Aeroflex (MACOM Technology Solutions) 기술: RF DIR COUPLER 5MHZ-1.5GHZ 6SMD 재고: 34558 pcs</p> <p>RFQ</p>	<p>MACP-011013 제조사: Aeroflex (MACOM Technology Solutions) 기술: RF DIR COUPLER 5MHZ-1.5GHZ 6SMD 재고: 75305 pcs</p> <p>RFQ</p>
<p>MACP-010563-TR1000 제조사: Aeroflex (MACOM Technology Solutions) 기술: RF DIR COUPLER 10GHZ-30GHZ 6TDFN 재고: 4446 pcs</p> <p>RFQ</p>	<p>MACP-011033 제조사: Aeroflex (MACOM Technology Solutions) 기술: RF DIR COUPLER 5MHZ-1.2GHZ 6SMD 재고: 34032 pcs</p> <p>RFQ</p>
<p>MACPCT0030 제조사: Aeroflex (MACOM Technology Solutions) 기술: RF DIR COUPLER 5MHZ-1.2GHZ 6SMD 재고: 27402 pcs</p> <p>RFQ</p>	<p>MACP-011010 제조사: Aeroflex (MACOM Technology Solutions) 기술: RF DIR COUPLER 5MHZ-1.2GHZ 6SMD 재고: 69745 pcs</p> <p>RFQ</p>
<p>MACP-011032 제조사: Aeroflex (MACOM Technology Solutions) 기술: RF DIR COUPLER 5MHZ-1.2GHZ 6SMD 재고: 33983 pcs</p> <p>RFQ</p>	<p>MACP-011038 제조사: Aeroflex (MACOM Technology Solutions) 기술: RF DIR COUPLER 5MHZ-1.2GHZ 6SMD 재고: 5028 pcs</p> <p>RFQ</p>