

Aeroflex (MACOM Technology Solutions)

Solutions

MACP-010563-001SMB

부품 번호:	MACP-010563-001SMB
제조업체 / 브랜드:	Aeroflex (MACOM Technology Solutions)
제품 설명	EVAL BOARD FOR MACP-010563-TR100
데이터 시트:	
RoHS 상태	무연 / RoHS 준수
재고 상태	4608 pcs stock
에서 운송된다	항공
선적 방법	DHL/Fedex/TNT/UPS/EMS

견적 요청

이미지는 표현 일 수 있습니다. 제품 세부 사항은 사양을 참조하십시오.

MACP-010563-001SMB의 명세

부품 번호	MACP-010563-001SMB
제조사	Aeroflex (MACOM Technology Solutions)
기술	EVAL BOARD FOR MACP-010563-TR100
무연 여부 / ROHS 준수 여부	무연 / RoHS 준수
사용 가능한 양	4608 pcs
데이터 시트	
유형	Power Detector
구성품	Board(s)
연속	-
다른 이름들	1465-1580
수분 민감도 (MSL)	1 (Unlimited)
무연 여부 / ROHS 준수 여부	Lead free / RoHS Compliant
회수	10GHz ~ 30GHz
함께 사용할 부품 / 관련 제품 용	MACP-010563

관련 태그

Aeroflex (MACOM Technology Solutions) MACP-010563-001SMB	MACP-010563-001SMB 대리점	MACP-010563-001SMB 공급 업체
MACP-010563-001SMB 가격	MACP-010563-001SMB 사진	MACP-010563-001SMB 이미지
MACP-010563-001SMB PDF 데이터 시트	MACP-010563-001SMB 데이터 시트 다운로드	MACP-010563-001SMB 데이터 시트
MACP-010563-001SMB 주석	MACP-010563-001SMB 구입	Aeroflex (MACOM Technology Solutions) MACP-010563-001SMB 구입
Aeroflex (MACOM Technology Solutions) MACP-010563-001SMB	Aeroflex (MACOM Technology Solutions) 공급 업체	Aeroflex (MACOM Technology Solutions) 대리점
Aeroflex (MACOM Technology Solutions) MACP-010563-001SMB	Aeroflex Circuit Technology MACP-010563-001SMB	Aeroflex MACP-010563-001SMB
Aeroflex (MACOM Technology Solutions) MACP-010563-001SMB	Aeroflex Metelics, Division of MACOM MACP-010563-001SMB	M/A-Com Technology Solutions MACP-010563-001SMB
Metelics (MACOM Technology Solutions) MACP-010563-001SMB	MACOM Technology Solutions MACP-010563-001SMB	

관련 상품

<p>MACP-010562-000000 제조사: Aeroflex (MACOM Technology Solutions) 기술: RF DIR COUPLER 6GHZ-18GHZ 6TDFN 재고: 4595 pcs</p> <p style="text-align: center; background-color: #ccc; padding: 2px;">RFQ</p>	<p>MACP-010563-TR1000 제조사: Aeroflex (MACOM Technology Solutions) 기술: RF DIR COUPLER 10GHZ-30GHZ 6TDFN 재고: 4446 pcs</p> <p style="text-align: center; background-color: #ccc; padding: 2px;">RFQ</p>
<p>MACP-010561-TR1000 제조사: Aeroflex (MACOM Technology Solutions) 기술: RF DIR COUPLER 2GHZ-6GHZ 6DFN 재고: 4662 pcs</p> <p style="text-align: center; background-color: #ccc; padding: 2px;">RFQ</p>	<p>MACP-010561-001SMB 제조사: Aeroflex (MACOM Technology Solutions) 기술: EVAL BOARD FOR MACP-010561-TR100 재고: 3678 pcs</p> <p style="text-align: center; background-color: #ccc; padding: 2px;">RFQ</p>
<p>MACP-011032 제조사: Aeroflex (MACOM Technology Solutions) 기술: RF DIR COUPLER 5MHZ-1.2GHZ 6SMD 재고: 33983 pcs</p> <p style="text-align: center; background-color: #ccc; padding: 2px;">RFQ</p>	<p>MACP-010562-001SMB 제조사: Aeroflex (MACOM Technology Solutions) 기술: EVAL BOARD FOR MACP-010562-TR100 재고: 5017 pcs</p> <p style="text-align: center; background-color: #ccc; padding: 2px;">RFQ</p>
<p>MACP-011010 제조사: Aeroflex (MACOM Technology Solutions) 기술: RF DIR COUPLER 5MHZ-1.2GHZ 6SMD 재고: 69745 pcs</p> <p style="text-align: center; background-color: #ccc; padding: 2px;">RFQ</p>	<p>MACP-010562-TR1000 제조사: Aeroflex (MACOM Technology Solutions) 기술: RF DIR COUPLER 6GHZ-18GHZ 6TDFN 재고: 3016 pcs</p> <p style="text-align: center; background-color: #ccc; padding: 2px;">RFQ</p>
<p>MACP-010563-000000 제조사: Aeroflex (MACOM Technology Solutions) 기술: RF DIR COUPLER 10GHZ-30GHZ 6TDFN 재고: 6556 pcs</p> <p style="text-align: center; background-color: #ccc; padding: 2px;">RFQ</p>	<p>MACP-011015 제조사: Aeroflex (MACOM Technology Solutions) 기술: RF DIR COUPLER 40MHZ-1.25GHZ 5SMD 재고: 24969 pcs</p> <p style="text-align: center; background-color: #ccc; padding: 2px;">RFQ</p>
<p>MACP-011014 제조사: Aeroflex (MACOM Technology Solutions) 기술: RF DIR COUPLER 5MHZ-1.5GHZ 6SMD 재고: 34558 pcs</p> <p style="text-align: center; background-color: #ccc; padding: 2px;">RFQ</p>	<p>MACP-011013 제조사: Aeroflex (MACOM Technology Solutions) 기술: RF DIR COUPLER 5MHZ-1.5GHZ 6SMD 재고: 75305 pcs</p> <p style="text-align: center; background-color: #ccc; padding: 2px;">RFQ</p>