






Leader Tech Inc.





이미지는 표현 일 수 있습니다. 제품 세부 사항은 사양을 참조하십시오.

59-CBSA-1.0X2.0X0.5

부품 번호:	59-CBSA-1.0X2.0X0.5
제조업체 / 브랜드:	Leader Tech Inc.
제품 설명	59 SERIES CBS SHIELD ASSEMBLY -  1.59-CBSA-1.0X2.0X0.5.pdf  2.59-CBSA-1.0X2.0X0.5.pdf
데이터 시트:	 무연 / RoHS 준수
RoHs 상태	5170 pcs stock
재고 상태	홍콩
에서 운송된다	DHL/Fedex/TNT/UPS/EMS
선적 방법	

견적 요청













59-CBSA-1.0X2.0X0.5의 명세

부품 번호	59-CBSA-1.0X2.0X0.5
제조사	Leader Tech Inc.
기술	59 SERIES CBS SHIELD ASSEMBLY -
무연 여부 / ROHS 준수 여부	무연 / RoHS 준수
사용 가능한 양	5170 pcs
데이터 시트	 1.59-CBSA-1.0X2.0X0.5.pdf  2.59-CBSA-1.0X2.0X0.5.pdf
폭 - 전체	1.000" (25.40mm)
통풍	Vent Holes in Pattern
유형	Shield, 2-Piece
연속	50-CBS
포장	Bulk
다른 이름들	59-CBSA-1.0X2.0X0.4 59-CBSA-1.0X2.0X0.4-ND
실장 형	Through Hole
수분 민감도 (MSL)	1 (Unlimited)
길이 - 전체	2.000" (50.80mm)
무연 여부 / ROHS 준수 여부	Lead free / RoHS Compliant
높이 - 전체	0.500" (12.70mm)
상세 설명	RF Shield Shield, 2-Piece 1.000" (25.40mm) X 2.000" (50.80mm) Vent Holes in Pattern Through Hole

관련 태그

Leader Tech Inc. 59-CBSA-1.0X2.0X0.5	59-CBSA-1.0X2.0X0.5 대리점	59-CBSA-1.0X2.0X0.5 공급 업체
59-CBSA-1.0X2.0X0.5 가격	59-CBSA-1.0X2.0X0.5 사진	59-CBSA-1.0X2.0X0.5 이미지
59-CBSA-1.0X2.0X0.5 PDF 데이터 시트	59-CBSA-1.0X2.0X0.5 데이터 시트 다운로드	59-CBSA-1.0X2.0X0.5 데이터 시트
59-CBSA-1.0X2.0X0.5 주식	59-CBSA-1.0X2.0X0.5 구입	Leader Tech Inc. 59-CBSA-1.0X2.0X0.5 구입
Leader Tech Inc. 59-CBSA-1.0X2.0X0.5	Leader Tech Inc. 공급 업체	Leader Tech Inc. 대리점
Leader Tech Inc. 59-CBSA-1.0X2.0X0.5		

관련 상품

<div><div>59-CBSA-1.0X1.5X0.5</div><div>제조사: Leader Tech Inc. 기술: 59-CBSA-1.0X1.5X0.5--59S45--CIRC 재고: 8186 pcs</div><div>RFQ</div></div>	<div><div>59-CBSA-1.0X1.0X0.5</div><div>제조사: Leader Tech Inc. 기술: 59 SERIES CBS SHIELD ASSEMBLY - 재고: 6305 pcs</div><div>RFQ</div></div>
<div><div>59-CBSA-1.0X1.5X0.4</div><div>제조사: Leader Tech Inc. 기술: 59 SERIES CBS SHIELD ASSEMBLY - 재고: 5649 pcs</div><div>RFQ</div></div>	<div><div>59-CBSA-1.0X1.75X0.5</div><div>제조사: Leader Tech Inc. 기술: 59 SERIES CBS SHIELD ASSEMBLY - 재고: 4770 pcs</div><div>RFQ</div></div>
<div><div>59-CBSA-0.75X6.0X0.5</div><div>제조사: Leader Tech Inc. 기술: 59 SERIES CBS SHIELD ASSEMBLY - 재고: 4422 pcs</div><div>RFQ</div></div>	<div><div>59-CBSA-1.0X1.25X0.5</div><div>제조사: Leader Tech Inc. 기술: 59 SERIES CBS SHIELD ASSEMBLY - 재고: 5272 pcs</div><div>RFQ</div></div>
<div><div>59-CBSA-1.0X3.5X0.5</div><div>제조사: Leader Tech Inc. 기술: 59 SERIES CBS SHIELD ASSEMBLY - 재고: 5743 pcs</div><div>RFQ</div></div>	<div><div>59-CBSA-1.0X3.25X0.5</div><div>제조사: Leader Tech Inc. 기술: 59 SERIES CBS SHIELD ASSEMBLY - 재고: 5294 pcs</div><div>RFQ</div></div>
<div><div>59-CBSA-1.0X2.75X0.5</div><div>제조사: Leader Tech Inc. 기술: 59 SERIES CBS SHIELD ASSEMBLY - 재고: 5006 pcs</div><div>RFQ</div></div>	<div><div>59-CBSA-1.0X2.25X0.5</div><div>제조사: Leader Tech Inc. 기술: 59 SERIES CBS SHIELD ASSEMBLY - 재고: 4732 pcs</div><div>RFQ</div></div>
<div><div>59-CBSA-1.0X2.5X0.5</div><div>제조사: Leader Tech Inc. 기술: 59 SERIES CBS SHIELD ASSEMBLY - 재고: 4550 pcs</div><div>RFQ</div></div>	<div><div>59-CBSA-1.0X3.0X0.5</div><div>제조사: Leader Tech Inc. 기술: 59 SERIES CBS SHIELD ASSEMBLY - 재고: 5995 pcs</div><div>RFQ</div></div>